



3A Composites GmbH
Alcan Composites
Alusingenplatz 1
D-78224 Singen

ZENTRALE:
A-4017 LINZ, PETZOLDSTRASSE 45-49, POSTFACH 27
TELEFON: 0732/7617-850, FAX: 0732/7617-89

www.ibs-austria.at - office@ibs-austria.at

BANKVERBINDUNGEN:
HYPO OBERÖSTERREICH, KTO.-NR. 00 0021294 4, BLZ 54000
IBAN: AT46540000000212944, SWIFT: OBLAAT2L
OBERBANK LINZ, KTO.-NR. 621-0060/55, BLZ 15000

DVR: 0659959, FN 89116d REGISTERGERICHT LINZ, UID-NR. ATU 23289705

2nd June 2010
Contact: Mr. Ing. Kibler/am
DW 818

**Prolongation of the validity of the Classification of Reaction to Fire Performance –
Report on classification of the burning behaviour of the building product
“Aluminium-sandwich system Dibond FR” – Report no.: 06033110ae**

With correspondence dated of 20th April 2010 you asked for the prolongation of the validity of the above mentioned Classification Report.

Product object:

„Aluminium-sandwich system Dibond FR“

Classification

In accordance with ÖNORM EN 13501-1:2002:

B – s1, d0

Validity:

The Classification Report No 06033110ae in relation with this correspondence has a new validity until **8th August 2012**.

On the end of this term there must be applied for the prolongation of the validity.

/2

ZWEIGSTELLEN:

A-1300 WIEN FLUGHAFEN, OFFICE PARK I, TOP B02, TELEFON: 01/22787330, FAX: 01/22787200
A-6020 SALZBURG, GINZKEYPLATZ 10/1, TELEFON: 0662/624222, FAX: 0662/624222-22
A-8100 VÖLKERMARKT, GRIFFNERSTR. 6, TELEFON: 04232/37026, FAX: 04232/37026-22
A-6020 INNSBRUCK, EDUARD-BODEM-GASSE 6, TELEFON: 0512/345509-0, FAX: 0512/345509-20
A-6850 DÖRNBERN, STEINEBACH 13, TELEFON: 05572/394299, FAX: 05572/394299-22





to the prolongation of the validity of Classification Report no 06033110ae- 3A Composites GmbH


If fundamental test features should be changed, the validity is extinguished before the two year time-limit. The validity is extinguished also, if the applicant attend inadmissible technical alterations and the in the test report stated dimensions will be passed over or under. The differences can move in the tolerance area (look test report).

Best regards,

**IBS - INSTITUTE FOR TECHNICAL FIRE PROTECTION AND
SAFETY RESEARCH GmbH**
Accredited testing and inspection institute


Ing. R. KIBLER
Official in charge


Ing. J. KRAML
Area manager, Testing Institute


Dir. Stv. Ing. H. PEHERSTORFER
Authorized officer
Managing director